




GDS3710 Connection & Wiring Diagrams ---- “Fail Safe” Electric Strike, 3rd Party Power Supply




GDS3710 Connection & Wiring Diagrams ---- “Fail Secure” Electric Strike, 3rd Party Power Supply




GDS3710 Connection & Wiring Diagrams ---- "Fail Safe" Electric Strike, 3rd Party Power Supply + POE




GDS3710 Connection & Wiring Diagrams ---- “Fail Secure” Electric Strike, 3rd Party Power Supply + POE



GDS3710 Connection & Wiring Diagrams ---- *Inappropriate* Electric Strike Connection



GDS3710 Connection & Wiring Diagrams ---- Good Electric Strike & High Power Device Connection



GDS3710 Connection & Wiring Diagrams ---- Wiegand RFID Reader

